FY2013 Marine Highways - Deferred Maintenance Inventory/Backlog

| Project Title | Project Cost (1,000's) | Project Description | Vessel or Location | Election District |
|------------------------------------|------------------------------|---|--------------------------|----------------------|
| HVAC System | (1,0000) | | | |
| Upgrade | 172.5 | HVAC Electric Humidifiers | Taku | 1-40 |
| Furnishing Renewal | | TV lounge chairs and other public space furnishing renewal | Taku | 1-40 |
| Painting Upgrades | 45.0 | Weather decks discharge piping vents rust removal and painting | Taku | 1-40 |
| Total Taku | 387.5 | | | |
| Crew Quarters | | Crew Quarters Furnishings Purser's Stateroom | | |
| Upgrades | 10.0 | (S/R 108) | Tustumena | 1-40 |
| Safety Upgrade | 10.0 | Deck and safety drawings general arrangement and signage corrections | Tustumena | 1-40 |
| Paint Renewal | | Fin stabilizer room platform painting | Tustumena | 1-40 |
| | | Trolley & beam on vehicle elevator & lifeboat davit | | |
| Safety Upgrade | 10.0 | stairs renewal | Tustumena | 1-40 |
| Communications | | | | |
| Upgrade | 10.0 | Intraship communications phone in first aid room | Tustumena | 1-40 |
| Engine Control | | · | | |
| Upgrades | 80.0 | Bridge wing main engine control upgrade | Tustumena | 1-40 |
| Passenger Area | | | | |
| Upgrades | 10.0 | Passenger cabins joinery upgrades | Tustumena | 1-40 |
| | | Passenger staterooms and first aid room | | |
| Furnishing Upgrades | 10.0 | furnishings | Tustumena | 1-40 |
| Crew Quarters | | | | |
| Upgrades | 20.0 | Crew quarters laundry and purser's office upgrades | Tustumena | 1-40 |
| Total Tustumena | 172.0 | | | |
| Total HD 1-40 | \$ 2,710.0 | | | |
| | | | | |
| Heating Control Upgrade | 150.0 | Remove existing pneumatic heating controls and replace with direct digital controls controls at Ketchikan Ferry Terminal (Risk Management Prop. No. 2549000536) | Ketchikan | 1 |
| <u> </u> | 130.0 | 140. 204300000) | Notollikali | <u> </u> |
| Sitka Terminal Roof Replacement | 75.0 | Remove and replace existing roof at the Sitka ferry terminal (Risk Mngmt Prop. No. 2549000830) | Sitka | 2 |
| Hydraulic Component | | Replace hydraulic controls and various components on main berth and LeConte berth at the Auke Bay | | |
| Replacement | 20.0 | ferry terminal | Juneau | 4 |
| | | Replace hydraulic components that have reached | Hoonah, | |
| Hydraulic Component | | the end of their useful life at AMHS unmanned | Metlakatla, | |
| Replacements | 45.0 | mooring facilities. | Kake | 5 |
| Total Shoreside | | | | |

| Total Marine | |
|-------------------|------------|
| Highways Deferred | |
| Maintenance | |
| Allocation: | \$ 3,000.0 |

Facilities

\$ 290.0